

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**

FIG. 1






FIG. 3




FIG. 4




FIG. 5 is a cross-sectional view of the device of FIG. 1, taken along line 5-5 of FIG. 1, showing the device in a closed position. The device includes a housing 13, a piston 15, a spring 18, a valve 80, and a seal 82. The piston 15 is biased by the spring 18 to the closed position, where the valve 80 is seated against the seal 82. The housing 13 is shown in cross-section, and the piston 15 is shown in a cross-sectional view.




FIG. 5

FIG. 6




FIG. 7

